

They Hold a Family's Fortunes







Each metal bracket supporting the truss-out scaffold must have at least three anchor bolts



Labour Department

Think of your family Work safety