



## Work Safety Alert Working Platform under Suspension at Height

1. **Date of Accident :** October 2012
2. **Place of Accident :** Reclamation works for construction of bridge near Tung Chung
3. **Summary :**

It is reported that while repairing the sheet piles fitted to a guide frame of a seawall cellular structure, a working platform suspended inside the guide frame suddenly collapsed, resulting in the death of one worker and injuries to 14 workers.

### 4. **Work Safety Alert for Contractors/Employers :**

Contractors/employers undertaking work-at-height on temporary structures should ensure that a comprehensive risk assessment is conducted and relevant safe working procedures are formulated. A working platform should not be used unless:

- its design, construction, installation, ascending/descending and suspension systems are certified safe by a professional engineer;
- safe means of access and egress are provided;
- it is regularly checked and certified safe by a competent person;
- every person undertaking erection, alteration or dismantling of the working platform is wearing a safety belt properly attached to an independent lifeline or a suitable anchorage;
- relevant safety training, information, instruction and supervision are provided to the workers involved;



- an effective preventive maintenance program to ensure proper maintenance of all parts of the working platform, including its ascending/descending and suspension system is established and implemented; and
- an effective monitoring system to ensure compliance with all the above safety measures and precautions is implemented.

## 5. Reference :

- [A Guide to the Factories and Industrial Undertakings Ordinance \(Section 6A\) - General Duties of Proprietors](#)<sup>1</sup>
- [A Guide to the Provisions for Safe Places of Work under Part VA of the Construction Sites \(Safety\) Regulations](#)<sup>1</sup>
- [Safe Systems of Work](#)<sup>1</sup>
- [Five Steps to Risk Assessment](#)<sup>1</sup>
- [Guidance Notes on Classification and Use of Safety Belts and their Anchorage Systems](#)<sup>1</sup>
- [Safety Hints on Operation of Suspended Working Platforms](#)<sup>1</sup>
- [Guidance Notes on Inspection, Thorough Examination and Testing of Lifting Appliances and Lifting Gear](#)<sup>1</sup>
- [Five Steps to Information, Instruction and Training](#)<sup>1</sup>

---

<sup>1</sup> Click to view the document



職業安全及健康部  
Occupational Safety and Health Branch  
勞工處  
Labour Department



\*\*\*\*\*

**DISCLAIMER**

This Work Safety Alert (“the Alert”) is issued at the earliest possible opportunity after a serious accident with a view to drawing the attention of interested parties to the general safety precautionary measures necessary to protect people engaging in similar work activities. The material contained in the Alert constitutes general guidance only. It does not reduce, limit, or replace, any legal obligations upon any person to comply with any statutory duties under relevant legislation. Users such as Managers and Supervisors should make their own evaluation of the information contained in the Alert to determine if it can be applied to their own situations and practices. The Labour Department does NOT accept any responsibilities for any loss or damage resulting from the use of or failure to use of the information on the Alert.