

Common **Unsafe** Conditions When Working at Height on Construction Sites

No safe access and egress is provided

In contravention of Regulation 38A of the Construction Sites (Safety) Regulations



The worker is climbing the formwork to access and exit the workplace

No personal fall protection equipment

In contravention of Regulation 38B of the Construction Sites (Safety) Regulations



The scaffolder is not provided with a safety belt and an independent lifeline

Unfenced excavation

In contravention of Regulation 40 of the Construction Sites (Safety) Regulations



Unfenced edges of an excavation



Labour Department




Occupational Safety and Health Council

Occupational safety and health enquiry hotline 2559 2297
Occupational safety and health complaint hotline 2542 2172
(All complaints will be treated in the strictest confidence)