



Work Safety Alert **Crushed by Minibus during Inspection**

- 1. Date of Accident :** July 2026
- 2. Place of Accident :** A vehicle repair workshop
- 3. Summary :**

While inspecting a minibus from underneath, a mechanic was crushed after the rear air bellow in a suspension system suddenly ruptured, causing the chassis to fall onto him. He was rushed to hospital and passed away the following day.

4. Work Safety Alert for Proprietors / Employers :

To prevent any workers from being endangered during the inspection, maintenance or repair of vehicles, proprietors/ employers should provide and maintain a safe system of work, including but not limited to the following precautionary measures:

- ensuring that vehicles are suitably and sufficiently supported before any person works underneath them;
- using suitable lifting equipment of sufficient capacity, such as a post lift, a hydraulic jack and axle stands, to lift and independently support the vehicle prior to any work underneath;
- ensuring that all lifting and supporting equipment is properly positioned and maintained in a safe working condition;
- ensuring that inspection of air bellows and related suspension components is conducted from a safe position;



- ensuring that no person enters or remains within danger zones susceptible to vehicle collapse or sudden air depressurisation;
- setting up and implementing an effective monitoring and control system for the inspection, maintenance or repair of vehicles; and
- providing all workers involved with necessary safety information, instruction and training, and ensuring that they are familiar with the safe work procedures and relevant safety measures.

5. Reference¹ :

- [Five Steps to Risk Assessment](#)
- [Safe Systems of Work](#)
- [Five Steps to Information, Instruction and Training](#)

DISCLAIMER

This Work Safety Alert (“the Alert”) is issued at the earliest possible opportunity after a serious accident with a view to drawing the attention of interested parties to the general safety precautionary measures necessary to protect people engaging in similar work activities. The material contained in the Alert constitutes general guidance only. It does not reduce, limit, or replace, any legal obligations upon any person to comply with any statutory duties under relevant legislation. Users such as Managers and Supervisors should make their own evaluation of the information contained in the Alert to determine if it can be applied to their own situations and practices. The Labour Department does NOT accept any responsibilities for any loss or damage resulting from the use of or failure to use of the information on the Alert.

Note: The material contained in the Alert is not exhaustive, and will be supplemented/ adjusted where necessary if more relevant information comes to light.

¹ Click to view documents